



Technical Bulletin
Parts and Service news

TB-60-99
10-20-99

To: All Harlan Tractor/Parts Customers

Subject: 02038-0038 Radiator

The Product Support Department has reported drawings with dimensional errors were sent to our vendors and shipped by Harlan to our customers.

The radiator can be readily identified by the absence of a cowl on the face of the engine side of the radiator and the outlet tube is not 1 3/4" it is 1 1/2". Also the mounting brackets are incorrect.

The conditions described are shown on the picture below, please contact your sales representative for a return authorization and Harlan will replace the non-conforming units as quickly as possible.

